

P17.31 - Barton Red Hill

Defect Id	Defect Location	Suburb	Asset Type	Remove existing 75-100mm & replace with 100mm concrete footpath (m2)	Remove existing 75-100mm & replace with 100mm concrete footpath with F72 mesh (m2)	100mm driveway (m2)	Remove & replace Kerb & Gutter (L/m)	Remove & replace pram crossing (count)	Remove & replace 50mm A/C road pavement or driveway (m2)	Special Instruction
50099	Adjacent 60 Macquarie Street	BARTON	Cycle path	14.79						
50099	Adjacent 60 Macquarie Street	BARTON	Cycle path	16.25						
50099	Adjacent 60 Macquarie Street	BARTON	Cycle path	7.80						
50103	Adjacent 60 Macquarie Street	BARTON	Cycle path	2.28						
50168	25 New South Wales Circuit	BARTON	Footpath	5.28						School crossing adjacent oval
59828	Corner Macquarie Street and Kings Avenue	BARTON	Footpath		4.00					
59830	Corner Macquarie Street and Kings Avenue	BARTON	Footpath		3.90					
61602	Adjacent 24 Brisbane Avenue Barton [on Macquarie Street]	BARTON	Footpath	1.44						
61603	Adjacent 24 Brisbane Avenue Barton [on Macquarie Street]	BARTON	Footpath	3.36						
61604	Adjacent 24 Brisbane Avenue Barton [on Macquarie Street]	BARTON	Footpath	2.88						

Defect Id	Defect Location	Suburb	Asset Type	Remove existing 75-100mm & replace with 100mm concrete footpath (m2)	Remove existing 75-100mm & replace with 100mm concrete footpath with F72 mesh (m2)	100mm driveway (m2)	Remove & replace Kerb & Gutter (L/m)	Remove & replace pram crossing (count)	Remove & replace 50mm A/C road pavement or driveway (m2)	Special Instruction
61605	Adjacent 24 Brisbane Avenue Barton [on Macquarie Street]	BARTON	Footpath	1.44						
61667	41 Blackall Street	BARTON	Footpath	4.65						Contact PAC's, Tree Root Damage, located adjacent to driveway
46104	Discovery Street BI 6 Sect 24	RED HILL	Shop Pave	12.83						Patch 1, Red Hill Shops.
46107	Corner Discovery/Lady Nelson BI 1 Sect 26	RED HILL	Footpath	7.29						Patch 5 adjacent Housing Estate.
46108	Discovery Street BI 1 Sect 26	RED HILL	Footpath	48.60						Patch 6 adjacent Housing Estate.
46108	Discovery Street BI 1 Sect 26	RED HILL	Footpath				2.40			Patch 6 adjacent Housing Estate.
46110	Discovery Street BI 1 Sect 26	RED HILL	Footpath	14.85						Patch 8 adjacent Housing Estate.
46124	Corner Discovery Street/Lady Nelson Place BI 1 Sect 25	RED HILL	Pram Crossing	6.08						Replace existing P/C with a Standard Pram Crossing.
46124	Corner Discovery Street/Lady Nelson Place BI 1 Sect 25	RED HILL	Pram Crossing					1		Replace existing P/C with a Standard Pram Crossing.
56044	Hindmarsh Drive	RED HILL	Footpath		6.20					Located on Hindmarsh Drive 100m west from Dalrymple St
56423	3 Cygnet Crescent	RED HILL	Footpath	1.68						Contact PAC's Tree Root Damage
60194	Opposite 93 Flinders Way	RED HILL	Footpath	6.24						Adjacent to entrance of School Oval,

Defect Id	Defect Location	Suburb	Asset Type	Remove existing 75-100mm & replace with 100mm concrete footpath (m2)	Remove existing 75-100mm & replace with 100mm concrete footpath with F72 mesh (m2)	100mm driveway (m2)	Remove & replace Kerb & Gutter (L/m)	Remove & replace pram crossing (count)	Remove & replace 50mm A/C road pavement or driveway (m2)	Special Instruction
62141	132 Monaro Crescent	RED HILL	Driveway	3.60						Contact PAC's, Tree Root Damage
62141	132 Monaro Crescent	RED HILL	Driveway			4.10				Contact PAC's, Tree Root Damage
67474	Red Hill Drive	RED HILL	Footpath						6.85	Contact PAT's, Tree Root Damage, Located at Red Hill Lookout tower
67474	Red Hill Drive	RED HILL	Footpath				10.00			Contact PAT's, Tree Root Damage, Located at Red Hill Lookout tower
66503	Opposite 4 Alexander Street	RED HILL	Pram crossing					1		Located on the corner of Mugga Way and Alexander St , Site specific TTM required?, Urgent Repairs Required
66503	Opposite 4 Alexander Street	RED HILL	Kerb				12.10			Located on the corner of Mugga Way and Alexander St , Site specific TTM required?, Urgent Repairs Required
66503	Opposite 4 Alexander Street	RED HILL	Asphalt						3.20	Located on the corner of Mugga Way and Alexander St , Site specific TTM required?, Urgent Repairs Required