

P17.22 Rivett Chapman Stirling

Defect Id	Defect Location	Suburb	Asset Type	Remove existing 75-100mm & replace with 100mm concrete footpath (m2)	100mm driveway (m2)	Remove & replace concrete OCI (L/m)	Special Instruction
56374	29 Gungurra Crescent	RIVETT	Driveway		10.56		
56375	29 Gungurra Crescent	RIVETT	Footpath	16.44			
56473	3 Angophora Street	RIVETT	Footpath	3.36			
56474	3 Angophora Street	RIVETT	Footpath	4.32			
57267	121 Darwinia Terrace	RIVETT	Driveway		6.16		
58518	71 Darwinia Terrace	RIVETT	Footpath			1.70	
58518	71 Darwinia Terrace	RIVETT	Footpath	2.04			
60471	Behind 43 Croton Street	RIVETT	Footpath	5.04			located in the parkland

Defect Id	Defect Location	Suburb	Asset Type	Remove existing 75-100mm & replace with 100mm concrete footpath (m2)	100mm driveway (m2)	Remove & replace concrete OCI (L/m)	Special Instruction
60472	Behind 43 Croton Street	RIVETT	Footpath	3.24			located in the parkland
47304	Fremantle Drive BI 2 Sect 24	STIRLING	Footpath	11.52			Patch 1 adjacent Retirement Village, Parkland
47305	Teesdale Place BI 2 Sect 24	STIRLING	Footpath	5.40			Patch 2 adjacent Canberra College Disused Tennis Courts
47306	Teesdale Place BI 2 Sect 24	STIRLING	Footpath	9.36			Patch 3 adjacent Canberra College Disused Tennis Courts
47308	Teesdale Place BI 2 Sect 24	STIRLING	Footpath	9.36			Patch 4 adjacent Canberra College Disused Tennis Court
47309	Teesdale Place BI 2 Sect 24	STIRLING	Footpath	21.96			Patch 5 adjacent Canberra College disused Tennis Court
47310	Teesdale Place BI 90 Sect 24	STIRLING	Footpath	19.44			Patch 6 adjacent Canberra College disused Tennis Courts
47316	Teesdale Place BI 90 Sect 24	STIRLING	Footpath	111.96			Patch 7 adjacent Weston Creek Football & Sports Club

Defect Id	Defect Location	Suburb	Asset Type	Remove existing 75-100mm & replace with 100mm concrete footpath (m2)	100mm driveway (m2)	Remove & replace concrete OCI (L/m)	Special Instruction
47317	Fremantle Drive BI 84 Sect 24	STIRLING	Footpath	1.44			Patch 8 adjacent Retirement Village
67773	64 Namatjira Drive	STIRLING	Driveway		18.25		
69300	18 Namatjira Drive	STIRLING	Footpath	3.36			
60413	94 Darwinia Terrace	CHAPMAN	Footpath	7.20			
60414	92 Darwinia Terrace	CHAPMAN	Footpath	1.44			
62661	Streeton Drive near Darwinia Terrace roundabout	CHAPMAN	Footpath	18.72			
62662	Streeton Drive near Darwinia Terrace roundabout	CHAPMAN	Footpath	4.68			
62663	Streeton Drive near Darwinia Terrace roundabout	CHAPMAN	Footpath	18.12			

Defect Id	Defect Location	Suburb	Asset Type	Remove existing 75-100mm & replace with 100mm concrete footpath (m2)	100mm driveway (m2)	Remove & replace concrete OCI (L/m)	Special Instruction
64756	162 Namatjira Drive	CHAPMAN	Footpath	21.60			
65476	170 Namatjira Drive	CHAPMAN	Footpath	19.80			
65477	170 Namatjira Drive	CHAPMAN	Footpath	12.60			
65478	170 Namatjira Drive	CHAPMAN	Footpath	16.56			
65652	160 to 154 Namatjira Drive	CHAPMAN	Footpath	4.92			
65653	160 to 154 Namatjira Drive	CHAPMAN	Footpath	4.20			
65654	160 to 154 Namatjira Drive	CHAPMAN	Footpath	5.04			
65655	160 to 154 Namatjira Drive	CHAPMAN	Footpath	9.36			
65656	160 to 154 Namatjira Drive	CHAPMAN	Footpath	3.00			
67041	140 Namatjira Drive	CHAPMAN	Footpath	4.20			

Defect Id	Defect Location	Suburb	Asset Type	Remove existing 75-100mm & replace with 100mm concrete footpath (m2)	100mm driveway (m2)	Remove & replace concrete OCI (L/m)	Special Instruction
67042	140 Namatjira Drive	CHAPMAN	Footpath	1.68			